


Instrumentation Metadata

Available on
website
When user
downloads data
from website,
metadata is also
downloaded
Continuing project



Snow depth data

Data available on

Further 2016 accomplishments

Evaporation gauge collected data all summer

Replaced broken barometer

Swapped many instruments for calibration

2016 provisional data provided on request

Created plan to clean underwater PAR sensor and attached buoy for easier maintenance

Replaced torn mesh panel on Pluvio wind shield

Calibrated both precipitation gauges

Updated website with new photos and instrumentation changes

Ongoing maintenance

Hourly air temperature

